

VIDHS

Figure 10. T303 Oil Cooler Drive Shaft Nut Torque Socket - Field Fabricated 91-10-00

Page 11 Revision 2